## United States Of America

## Department of Transportation - Federal Abiation Administration

## Supplemental Type Certificate

Number SA09173AC

This Certificate issued to

New Systems 1201 North Industrial Blvd. Round Rock, TX 78681

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product Type Certificate Number:

A24CE

Make: Beech

Model: 200, 200C, 200CT, 200T, A200C

B200C, B200CT, B200T

Description of Type Design Change:

Installation of AirCell ACM-2000 Transceiver in accordance with New Systems Master Drawing List, 182-00-0001, Dated 10-09-95, or later FAA approved revision.

Limitations and Conditions:

Compatibility of this design change with previously approved modifications must be determined by the installer.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, recoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 15, 1995

Date reissued : March 21, 1997

Date of issuance: October 23, 1995

Date amended:

By direction of the Administrator

Michele M. Owsley

Manager, Airplane Certification Office

Southwest Region

(Title)

Electronic Engineering Services, R&D and Manufacturing 1201 North Industrial Blvd Round Rock, Texas 78681 (512) 388-4808 / FAX (512) 388-6020

May 12, 1998

Ms. Susie Zavala ASW-103 Department of Transportation Federal Aviation Administration Ft. Worth, Texas 76137-0103

Dear Ms. Zavala:

We have found an error on two of the STC's that were reissued to us when we moved from Pflugerville to Round Rock in October, 1996. The STC's are SA09171AC for the Cessna 501 and 551; and SA09173AC for the Beech 200 series aircraft.

On STC number SA09171AC, the Type Certification Number needs to be corrected. Under the heading "Original Product Type Certificate Number", the TC Number should be A27CE for the Cessna 501 and 551.

On STC number SA09173AC, the Master Drawing List needs to be corrected. Under the heading "Description of Type Design Change", the Master Drawing List should be ...182-00-0001, dated 10-09-95 or later FAA approved revision.

We are requesting that the STC's be reissued with the correct TC number and Master Drawing List added. I have enclosed the original of the STC's for correction. Also, for you reference, I have enclosed a copy of the "old" STC's that was issued to us at our Pflugerville address. Please note that I have highlighted the changes.

Thank you for your help, and if you have any question, please call me at 512-388-4808.

Sincerely,

Robert M. Hurley

Ma of myly

 $\label{eq:instructions: Instructions: The transfer endorsement below may be used to notify the appropriate FAX Regional Office of the transfer of the Supplemental Type Certificate.$ 

The FAA will reissue the certificate in the name of the transferee and forward it to him.

## TRANSFER ENDORSEMENT

Transfer the ownership of Supplemental Type Certificate Number
to (Name of transferee)
(Address of transferee)
(Number and street)
(City, State, and ZIP code)
from (Name of grantor) (Print or type)
(Address of grantor)(Number & street)
(Number & Street)
(City, State, and ZIP code)
Extent of Authority (if licensing agreement):
Date of Transfer:
Date of Transfer:
Signature of grantor (In ink):